

Castor update

Safety is a process. At JOWI, we focus on improving safety year on year – working together with you to improve on previous benchmarks:

- You carry out the planned inspections in your operations.
- We remain at your disposal with our retrofit services and helpful advice.



Inspect castors to ensure full working order.

Please check the state of your steering castors and brakes today – and at least once a year.

Important: The bolts on the castors must be tightened to a torque of between 80 and 100 Nm.



Replace castor bolts on older models.

We recommend that you replace the securing screws, including washers, on all racks that were delivered 2014. An audit that JOWI commissioned has revealed that transporting standard loads can cause screws to become loose.



A complimentary update pack.

We will be pleased to send you a complimentary set of bolts and wedge-lock washers for the castors on your JOWI Mobile/Transport Racks – including the necessary tools for the job!

Can we help with any queries?

Josef Winkler
Tel.: +43 2743 3844 88
josef.winkler@jowi.at

www.jowi.at